

Waste Minimization/ Energy Efficiency Workshop
DRAFT AGENDA
Electrotechnology Applications Center
Northampton Community College
Bethlehem, PA

Tuesday, June 3, 2003

8:00 a.m. - 8:30 a.m.	Continental Breakfast Check In
8:30 a.m. - 9:00 a.m.	Introductions and Review of Training Schedule ● EPA Region III · Electrotechnology Applications Center · Baldwin Hardware · Review of Training Schedule
9:00 a.m. - 10:00 a.m. Energy Supply and Costs	Energy Usage Overview · Industrial Energy Consumption ●
10:00 a.m. -10:15 a.m.	Break
10:15 a.m. -12:00 p.m.	Energy Consuming Systems and Common ECOs ● Motor Systems Lighting and HVAC
12:00 noon - 1:00 p.m.	Lunch
1:00 p.m. -3:00 p.m.	Energy Consuming Systems and Common ECOs · Air Compressors · Boilers and Process Heat ●· Pumping Systems
3:00 p.m. - 3:15 p.m.	Break
3:15 p.m. - 4:30 p.m.	Waste Minimization Training (EPA)
4:30 p.m. - 5:00 p.m.	Overview of Assessment Tasks · Preparing for the Assessment (Review of Baldwin Hardware data) ● Assessment Methodology

Waste Minimization/ Energy Efficiency Workshop
DRAFT AGENDA
Electrotechnology Applications Center
Northampton Community College
Bethlehem, PA

Wednesday, June 4, 2003

Baldwin Hardware Company: Site Visit Details to be announced

Thursday, June 5, 2003

8:00 a.m. - 8:30 a.m.	Continental Breakfast
8:30 a.m. - 9:00 a.m.	Assessment Report Format (EPA)
9:00 a.m. - 10:00 a.m.	Assessment Measures Brainstorming
10:00 a.m. - 10:15 a.m.	Break
10:15 a.m. - 11:00 p.m.	Review of Energy Spreadsheet Tools
11:00 a.m. - 12:00 p.m.	Report Development - Waste Minimization Measures
12:00 p.m. - 1:00 p.m.	Lunch
1:00 p.m. - 3:00 p.m.	Report Development - Energy Measures
3:00 p.m. - 3:15 p.m.	Break
3:15 p.m. - 4:00 p.m.	Information Resources and Open Discussion